

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From,
Sri. Y.V. Kishore Babuji. B.Tech,
Executive Engineer (R&B)
(R&B) Division, Eluru,

✓ To,
The Principal,
PV Krishna Rao Memorial,
Kumar EM School Door.No.2-187,
Kothuru (V) Boorvancha Panchayat,
Nuzvidu Mandal,
Eluru District.

Lr.No:259/Soundness Certificate/JA/2020, Dt: 14/08/2025.

Sir,

Sub:-Works (R&B) Division, Eluru- Correspondent PV Krishna Rao Memorial Kumar EM School - Door.No.2-187,Kothuru Village Boorvancha Panchayat - Nuzvidu Mandal in Eluru District. – Soundness Certificate - Issued- Regarding.


Ref: -1.Lr.No.Nill Recived on Dt.11.08.2025.

2.Letter.No. Soundness Certificate -Kumar/DEE/NZD/2025, Dt.13.08.2025. of
Dy E E (R&B) Sub- Division Nuzvid.

With reference to above, it is informed that the RCC G+2, roof building of existing building of PV Krishna Rao Memorial Kumar EM School - Door.No.2-187,Kothuru Village Boorvancha Panchayat - Nuzvidu Mandal in Eluru District. is structurally sound to run the classes for a period of one year i.e. form **13.08.2025 to 12.08.2026**.


Enclose: Soundness Certificate.

Yours faithfully,


Executive Engineer (R&B)
(R&B) Division, Eluru.
14/8/25

SOUNDNESS CERTIFICATE

1	Name of the College & Address	P.V KRISHNA RAO MEMORIAL KUMAR EM SCHOOL .D.No. 2-187 BORAVANCHA PANCHAYAT, NUZVID MANDAL, ELURU DISTRICT
2	Name of the Management and Phone number	DR.SURVEPALLI RADHA KRISHNA EDUCATIONAL & CULTURAL SOCIETY
3	Date of Inspection	13.08.2025
4	Year of Construction	2020
5	Type of the Building	RCC Roofed Structure
6	Type of the foundation	Open foundation
7	Present Condition of foundation whether any settlement cracks are observed upto basement level	Not Observed
8	Soundness of superstructure whether any cracks out of plumb in walls noticed	Not Observed
9	Soundness of Structure	Structurally sound & Safe
10	Condition of flooring	Structurally sound
11	Condition of ACC Sheet Roof etc.,	-----
12	Any other remarks which are required to ensure the structural soundness	The inspection certificate does not covering all the aspects of the work and designs
13	Valid up to	12.08.2026
<p>Note:</p> <p>1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in future.</p> <p>2) Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students. (Such as cyclones severe weather conditions, Tsunamis, earthquakes etc.,)</p> <p>3) Department is not responsible for any structural changes to the building in future course of time.</p>		


Executive Engineer
(R&B) Division, ELURU
 14/8/25


Deputy Executive Engineer
(R&B) Sub Division, Nuzvid