

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From,
Sri.Y.V.Kishore Babuji. B.Tech,
Executive Engineer (R&B
(R&B) Division, Eluru,

To,
The Principal,
P.V. Krishna Rao Memorial Kumar E.M School,
Door No: 2-187,
Kothuru Village Boorvancha Panchayat,
Nuzvid Mandal,
Eluru District.

Lr.No:259/Soundness Certificate/JA/2020 -1 Dt: 18/09/2026.

Sir,

Sub:- Works (R&B) Division, Eluru - P.V. Krishna Rao Memorial Kumar E.M School.
Door No: 2-187, Kothuru Village Boorvancha Panchayat, Nuzvid Mandal,
in Eluru District. - Soundness Certificate - Issued- Regarding.

Ref: -1. Your Lr.No.Nill. Dated: 11.09.2026.

2. Letter.No. Kumar School /DEE/NZD/HC/2022-23, Dt: 15.09.2026. of the Deputy
Executive Engineer (R&B) Sub-Division Nuzvid.

With reference to above, it is informed that as per the request of Correspondent dated 15.09.2026 the RCC (G+3) Building P.V. Krishna Rao Memorial Kumar E.M School, Door No: 2-187, Kothuru Village Boorvancha Panchayat, Nuzvid Mandal, in Eluru District. was inspected and it is structurally sound to run the classes for a period of One year (i.e.) from 15.09.2026 to 14.09.2027.

Enclose: Soundness Certificate.

Yours faithfully,

M.V. Kishore
18/9/2026
Executive Engineer
(R&B) Division, Eluru.

18/9/26



SOUNDNESS CERTIFICATE

1	Name of the School & address	P.V KRISHNA RAO MEMORIAL KUMAR EM SCHOOL, D.No.2-187, BORVANCH PANCHAYAT ,Nuzvid Mandal Eluru District, A.P
2	Name of the Management and phone number	DR. SURVAPALLI RADHA KRISHNA EDUCATIONAL SOCIETY, Nuzvid Mandal Eluru District, A.P Ph No.910058622,88522031368
3	Date of Inspection	15.09.2026
4	Year of Construction	2020
5	Type of the Buildings	RCC ROOFED STRUCTURE(G+3)
6	Type of the foundation	Open foundation
7	Present Condition of foundation whether any settlement cracks are observed upto basement level	Not observed
8	Soundness of superstructure whether any cracks out of plumb in walls noticed	—
9	Soundness of Girders, Trusses etc	—
10	Condition of the Roofing	Structurally Sound
11	Condition of Roof sheets, GI Sheet etc	—
12	Any other remarks which are required to ensure the structural soundness	The inspection certificate does not covering all the aspects of the work and design
13	Valid up to	14.09.2027

Note:

1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in future.

2) Further the Management has to take necessary precautions natural calamities occur from time to time for the safety of the students. (Such as cyclones severe weather conditions, Tsunamis, earthquakes etc

3) Department is not responsible for any structural changes to the buildings in future course of time.

[Signature] 15/9/26
Deputy Executive Engineer
(R&B) Sub-division, Nuzvid

// Contd signed //
[Signature] 18/9/2026
Executive Engineer
(R&B) Division, ELURU
18/9/26

